

APPLICATION FOR REPORT OF SYSTEM STATUS

ON0116665

SR0235431

03/07/2019

O&M Record # (Office Use)

RSS Application # (Office Use)

Closing Date

Mail To Information

Dan Thompson

Name

2721 Slippery Hill dr nw

Address

Gig Harbor, WA 98332

City/State/Zip

(253) 381-3474

Phone

Site Information

Dan & Kerri Thompson

Owner Name

2828650080

Parcel

5609 76th Street Ct E

Site Address

Puyallup, WA 98373

City/State/Zip

RSS Validation

WEB PAYMENT
RECEIVED
03/04/2019

8 Canyon Lane Estates 17878

Lot#	Subdivision	# of buildings	Lot Size in Sq Ft
Building Type:	Single Family ☐	Multi Family ☐	Mobile Park ☐
	Food Service ☐	Commercial ☐	Institutional ☐

Water Supply:

☒ Public Water Company: SUMMIT WATER & SUPPLY CO ID: 85050V
☐ Individual Well ☐ Spring

System Information:

- Current # of Occupants: 4
- Vacant? ☐ Yes ☒ No If vacant how long? na
- Garbage Disposal? ☐ Yes ☒ No 4. Number of Bedrooms: 4
- Have any septic system malfunctions occurred during your ownership of this property? ☐ Yes ☐ No ☒ Unk
- Have any alterations or repairs been made to the septic system during your ownership? ☐ Yes ☐ No ☒ Unk

If you answered 'Yes' to either question 5 or 6 you must provide a brief description and attach any receipts (if available).

I certify that the information on this application is true and correct to the best of my knowledge, and I understand I can be held liable for making false statements. I am authorized by the legal property owner to request inspection for this location and grant consent to employees of the Tacoma-Pierce County Health Department to allow access to this property for inspection related to this application.

WEB APPLICATION

Signature

Date

Additional Information:

Fax To:

Fax #: WEB APPLICATION

Microfilm Records

2004 ps
1986 Deacey

Please allow 10 working days
for inspection of the
property to be completed



19-00793



On-Site Sewage Operation and Maintenance Program Report of System Status (For Real Estate)

Mail To Information:

DAN THOMPSON
2721 SLIPPERY HILL DR NW
GIG HARBOR WA 98332

Phone: (253) 381-3474

Site Address:

5609 76TH STREET CT E
PUYALLUP WA 98373
Parcel # 2828650080

Fax: **WEB APP**

Fax To:

TPCHD Record Number

SR0235431

Closing Date:

03/07/2019

Issued Date:

03/15/2019

Dwelling Type: Duplex

Garbage Disposal: N

of Bedrooms stated by applicant: 4

Water System Information:

Water System Type: Public

State Water ID: 85050V

Water System Name: SUMMIT WATER & SUPPLY CO

Inspection Results for:**Report of System Status (For Real Estate)**

Field Inspection Completed on: 03/15/2019

Field Inspection Completed by: Mike Free

RSS Issued By: Mike Free

Telephone # : (253) 798-6058

**Meets requirements for system evaluation and compliance
with Environmental Health Code, Chapter 2.**

Onsite Sewage System Information:

O&M Record #: ON0116665

Program Element: 0620

System Classification: Moderate Risk: Requires inspection
every three years.

Approved or Estimated

Wastewater Gallons Per Day: 480

System Description:

Gravity

Inspector Comments:

- Septic system appears to be functioning at time of inspection; no surfacing sewage found.

Note: This is the Official Report of System Status.

Valid for 12 months from Issued Date.

Any person aggrieved by a decision of the health officer shall have the right to appeal such decision, in writing, within fifteen (15) days in accordance with the appeal procedures set forth in Environmental Health Code, Chapter 1.

Tacoma-Pierce County Health Department
Environmental Health Division
3629 S D Street, MS-1035
Tacoma, WA. 98418-6813

Phone: (253) 798-7392 Fax: (253) 798-7663

Site Address: 5609 -11 76th Street CT E Puyallup, WA 98373

Record ID: SR0235431

Closing Date: 03/07/2019

Dwelling Type: Duplex

of Bedrooms: 4 ✓

Garbage Disposal: No ✓

Components: Gravity ✓

Inspector's Signature/Date:

M. F. 3/14/19

O&M Record #: ON0116665

Waste Water Gallons Per Day: 500 *480*

System Type: O&M Simple Septic System/Registration

Shared? 0620

- ☒ Septic system appears to be functioning at time of inspection (no surfacing sewage found).
- ☐ Septic system appears to be functioning but system was not in use at time of inspection.
- ☐ Exact location of the drainfield cannot be verified (no asbuilt drawing found).
- ☐ Drainfield is sized for ___ bedrooms per Health Department records.
- ☐ Septic system was not designed to include a garbage disposal.
- ☐ Use of a garbage disposal unit is not recommended.
- ☐ This is an area of high winter water tables and/or marginal soils.
- ☐ Drainfield is located on an easement addressed as _____.
- ☐ Part of the drainfield appears to be covered by a structure or impervious surface.
- ☐ Part of the drainfield appears to be covered by a sport court.
- ☐ Small constructed pond or fountain appears to be located in the drainfield area.
- ☐ Landscaping material placed over drainfield must allow air passage into soil.
- ☐ Green striping with lush plant growth noted in drainfield area.
- ☐ Vehicle traffic over drainfield or reserve area is not recommended.
- ☐ Drainfield is located in a pasture and may be impacted by livestock.
- ☐ Fire pit in drainfield area is not recommended.
- ☐ Health Department records indicate the water well serving this property has not received final approval.
- ☒ RME OK

RSS on Hold for:

- ☐ Drainfield area was overgrown with brush / blackberries and could not be inspected; clear the drainfield area.
- ☐ A field inspection revealed that there is an abandoned well on your property.
- ☐ Septic system appears to be malfunctioning at the time of the inspections: _____

This application is on hold for receipt of additional inspection or other information. Check below:

- ☐ Health Department staff observed the tank or pump lid is not properly secured.
- ☐ Missing RME report
- ☐ Deficient RME report: _____
- ☐ Community System not current with the O&M inspection requirements.
- ☐ An unapproved septic system or component was installed on the property.